

## Deterioration of thin marble cladding - *A comprehensive literature update.*

### Literature list of May 1<sup>st</sup> 2004

| Author 1                 | Title  | Book/Journal  |
|--------------------------|--|---|
| Adams, Eric              | Wintry discontent (Finlandia City Hall)  | Architecture, October 1998  |
| Aires-Barros, L., Et al. | Dry and wet laboratory tests and thermal fatigue of rocks  | Engineering Geology, 9, p. 249-265, 1975  |
| Alesiani, M.<br>Et al.   | Evaluation of stone pore size distribution by means of NMR   | 9th International Congress on deterioration and conservation of stone, Venice 19-24 June, 2000                                |
| Alessandrini, G., Et al. | Investigations on the decay of Candoglia marble used in the Milan Duomo  | Proc. Of the Int. Symp. On the conservation of stone, Bologna, June, 1975   |
| Algeo, H.L.              | What the specification writer needs from the stone industry.   | Construction Specifier, April 1961  |
| Alnæs, L.                | Quality and durability of natural stone. Influencing factors and test methods. (In Norwegian, summary in English)  | Dr.ing-thesis No. 1995:5. Institute for geology and mineral resources engineering, University of Trondheim, NTH, Norway, 1995 |
| Alnæs, L., Et al.        | Influence of mineral and rock properties on bowing and strength loss of marble claddings – Discussion paper based on status of work in the TEAM project. | 9 <sup>th</sup> Euroseminar on microscopy applied to building material, Trondheim, Norway, September 2003.                    |
| Alnæs, L., Et al.        | Influence of rock and mineral properties on the durability of marble panels.   | Proceedings Dimension Stone 2004, International Conference, Prague, Czech Republic. (In prep.), 2004                          |
| Amrhein, J.E.,<br>Et al. | Designing successful stone slab veneer   | Stone World, Nov., pp. 46-, 1993  |
| Azzoni, A.,<br>Et al.    | Valutazione con prove meccaniche, chimico-fisiche e petrografiche del degrado indotto su alcune rocce mediante varie tecniche di laboratorio.            | Bollettino della Associazione Mineraria Subalpina, Anno XXIX, n. 2-3, pp. 209-221, 1992                                       |
| Babbitt, T.F.            | Thin-Stone veneers offer unique design and performance demands   | Journal, Volume 15 Number 3, Hoffmann Architects, 1997  |
| Bain, G.W.               | Geological, chemical and physical problems in the marble industry  | American Institute of Mining and Metallurgical Engineers, technical publication, no. 1261, p. 16, 1940                        |
| Bain, G.W.               | Measuring grain boundaries in crystalline rocks  | N/A   |
| Bain, G.W.               | Calcite marble   | Economic Geology, Vol. XXIX, No. 2, Mar-Apr., 1934  |
| Bain, G.W.               | Mining marble  | Mining and metallurgy, June, 1935   |
| Bain, G.W.               | The central Vermont marble belt  | New England intercollegiate geological ass., 34th annual meeting, 1938  |
| Bain, G.W.               | Geologic History of the Green Mountain Front   | Fifteenth Biennial Report of the Vermont State Geologist, 1925-1926, pp. 222-241, 1926  |
| Bain, G.W.               | Stone definitions  | Research Department Notes, October 1938, Vermont Marble Company Research Department.  |
| Bain, G.W.               | Marble warping   | Misc. Private communications  |
| Bain, G.W.               | Spontaneous rock expansion   | The Journal of Geology; The University of Chicago, Volume XXXIX, No. 8, November-December 1931                                |
| Bain, G.W.               | Petrology of Marble  | Reprinted from the Mineralogist, Portland, Oregon, 1936   |
| Barsottelli, M., Et al.  | Microfabric and alteration in Carrara marble: a preliminary study  | Science and Technology for Cultural Heritage 7 (2), pp.115-126, 1998  |
| Bello, M.A., Et al.      | Scanning electron microscopy to establish the marble weathering mechanism in the Alhambra of Granada (Spain)   | Scanning Microscopy, 5(3), pp. 645-52, 1991   |
| Bertagnini, A., Et al.   | Il marmo cotto in natura e nei monumenti   | Rendiconti della Società Italiana di Mineralogia e Petrologia, 39 (1), pp. 39-46  |
| Biolzi, L., Et al.       | Mechanical characterization of natural building stone.   | Degradation of Natural Building Stone, Geotechnical Special Publication No. 72, ASCE., 1997                                   |
| Bonnell, D.G.R., Et al.  | The thermal expansion of concrete  | National Building Studies, Technical Paper No. 7, 1951  |
| Bortz, S.A.,             | Some field problems with thin veneer building stones   | ASTM STP 996, ed. B. Donaldson, pp. 11-31, 1988   |

|                                   |   |  |
|-----------------------------------|---|--|
| Et al.                            |   |  |
| Bortz, S.A.,<br>Et al.            | Laboratory evaluation of building stone weathering  | Degradation of Natural Building Stone, Geotechnical Special Publication No. 72, pp 85-104, 1997                    |
| Bortz, S.A.                       | Review of Durability Testing in the United States and Europe  | ASTM Symposium, New Orleans, 1999  |
| Bortz, S.A.,<br>Et al.            | Review of durability testing in the United States and Europe  | STP 1394 Dimension Stone Cladding: Design, Construction, Evaluation and Repair, November, 94-109, 2000             |
| Bouineau, A.,<br>Et al.           | Faudra-t-il renoncer aux facades en marbre agrafe   | Les Camiers Techniques ou Batiment, No. 147, pp. 32-35, 1995   |
| Bouineau, A.,<br>Et al.           | La decohesion granulaire maladie des revetements de facades en marbre   | Mines et Carrieres - Industrie Minérale, pp. 69-77, 1995   |
| Bradley, Frederick                | Guide to the Marble Quarries in Carrara   | Internazionale Marmi E Macchine Carrara, 1991  |
| Brocco, D.,<br>Et al.             | Air pollution in Rome and its role in the deterioration of porous building materials                                      | Durability of building materials, 5, pp. 393-408, 1988   |
| Building Design &<br>Construction | Amoco Tower retrofit underscores problems with marble veneers. (problems such as thermal cycles and pollutants)           | Building Design & Construction 6/1/1989  |
| Burn, K.N.                        | Performance of stone facades  | Building Science Insight '84 - Institute for Research in Construction, 1984  |
| Calia, A., Et al.                 | A research into intrinsic parameters material to the durability of highly porous building stones                          | 9th Int. Congress on deterioration and conservation of stone, Venice 19-24 June, 2000                              |
| Cantisani, E. Et al.              | Relationships between microstructures and physical properties of white Apuan marbles: inferences on weathering durability | Periodico di Mineralogia, 69, 3, pp. 257-268, 2000   |
| Cattaneo, Sara; Labuz,<br>J.F.    | Damage of Marble from Cyclic Loading  | Journal of Materials in Civil Engineering, Nov./Dec. 2001, pp. 459-465.  |
| Cavallucci, F.,<br>Et al.         | Mechanical decay process in lapideous materials (Carrara marbles): Preliminary study of creep phenomena                   | Proc. 4th Int. Symp. on the Conservation of Monuments in the Mediterranean, pp. 91-100, 1997                       |
| Celestino, T. Et al.              | Fracture Mechanics of Marble using a splitting tension test   | Journal of Materials in Civil Engineering, Nov./Dec. 2001, pp. 407-411   |
| Cheng, R.J., Et al.               | A study of marble deterioration at City Hall, Schenectady, New York.  | Journal of the air pollution control association 34 (1), pp. 15-19, 1984   |
| Cheng, R.J., Et al.               | Deterioration of marble structures - The role of acid rain  | Analytical Chemistry, 59(2), pp. 104A-106A, 1987   |
| Chin, I.A.<br>(editor)            | Seminar on recladding of the Amoco building in Chicago, Illinois  | Proceedings, Chicago Committee on High Rise Buildings, Report no. 15, Nov. 1995                                    |
| Chin, I.R., Et al.                | Design of thin stone veneers on buildings   | Building Stone Magazine, May/June, 1986  |
| Chin, I.R., Et al.                | Testing for thin stone veneers on buildings   | Masonry Construction, March 1991 & July  |
| Chin, Ian R.                      | Common causes of failures of stone claddings on buildings   | STP 1394 Dimension Stone Cladding: Design, Construction, Evaluation and Repair, November, pp 151-161, 2000         |
| Cohen, J.M., Et al.               | Durability and integrity of marble cladding: "A state of the art review"  | Journal of the performance of constructed facilities, 5(2), pp. 113-124, 1991                                      |
| Cooke, R.U., Et al.               | Using gravestones to assess changing rates of weathering in the United Kingdom.   | Earth Surface Processes and Landforms, Vol. 20, pp. 531-546, 1995  |
| Colback, P.S.B., Et al.           | The influence of moisture content on the compressive strength of rocks  | Proceeding of the Rock Mechanics Symposium - 3RD Canadian Symposium, Toronto, pp 65-83, 1965                       |
| Cooper, H.W., Et al.              | The effect of cracks on the thermal expansion of rocks  | Earth and Planetary Science Letters, 36, pp 404-412, 1977  |
| Charitaras, B.                    | Weathering evaluation of stones using ultrasonic techniques.  | Proc. Eurocare - Euromarble, EU 496 - Workshop 7, October 1996, Patras, Greece.                                    |
| Crnkovic, B, Et al.               | On the investigation of stone quality for the reconstruction of the sehiluci monument near Banja Luca                     | 2nd internaional symposium on the Deterioration of Building Stone, pp. 185-192, 1976                               |
| Dal Pino, R.,Et al.               | A SEM investigation on fatigue damage of marble   | J. of Mat. Sci. Letters 18 p. 1619-1622, 1999  |
| Dean, N.E.                        | Geochemistry and archaeological geology of the Carrara marble, Carrara, italy   | Classic marble: geochemistry, technology, trade, eds. Harz and Waelkens, Kluwers academic publ., pp. 315-323, 1988 |
| Dolske, D.A. and<br>Meakin, J.D.  | Acid deposition impacts on historic bronze and marble statuary and monuments.   | Materials Performance, November 1991   |
| Dorris, V.K.                      | T&P Technology: Anchoring thin-stone veneers  | Architecture, December 1993  |

|                            |  |   |
|----------------------------|--|---|
| Dragovich, D.              | Marble weathering in an industrial environment, eastern Australia  | Environ. Geol. Water Sci., 17(2), pp. 127-32, 1991  |
| Dunakin, R.                | Mechanical and Environmental Studies of Marble Deterioration   | Licentiate Thesis, Kungl. Tekniska Högskolan, Stockholm, ISBN 91-7283-099-9, 2001   |
| Erlin, B.                  | Contribution to a better understanding of the mechanism causing dishing failures of the Carrara marble when used for outside building facades. | STP 1394, ASTM Symposium on Dimension Stone Cladding: Design, Evaluation, Construction and Repair. pp. 71-78. October 27. New Orleans, 1999 |
| Erlin, B.                  | When is a bow not a bow?   | Stone World, Feb. 1989  |
| Erlin, B.                  | Contribution to a better understanding of the mechanism causing dishing failures of the Carrara marble when used for outside building facades  | STP 1394 Dimension Stone Cladding: Design, Construction, Evaluation and Repair, November, pp 71-79, 1999                                    |
| Farrar, Bill               | Recladding City Hall, City of Richmond, Virginia   | RichmondGov.com, 2000   |
| Fassina, Vasco             | New findings on past treatments carried out on stone and marble monuments surfaces.  | The Science of the Total Environment 167, 1995, pp. 185-203, 1995   |
| Feddema, J.J., Et al.      | Marble weathering and air pollution in Philadelphia  | Atmospheric Environment, Vol. 21, No. 1, pp. 143-157, 1987  |
| Ferrero, A.M. ; Marini, P. | Technical Note: Experimental Studies on the Mechanical Behaviour of two Thermal Cracked Marbles.   | Rock Mechanics and Rock Engineering, 34 (1), pp. 57-66, Springer-Verlag, 2001   |
| Fimmel, R. and Bayer, K.   | Weathering behaviour of marble in Alpine regions.  | Proc. Eurocare – Euromarble, EU 496 – Workshop 7, October 1996, Patras, Greece.   |
| Ford, E.                   | The Theory and Practice of Impermanence.   | Harvard Design Magazine, Fall 1997  |
| Forlani, G., Et al.        | Proposta per una caratterizzazione microstrutturale dei conglomerati naturali (Resume in English)  | Studi e ricerche Vol. 21, 2000  |
| Franzini, M., Et al.       | Degradazione del marmo per effetto di variazioni di temperatura  | Società Italiana di Mineralogia e Petrologia, 39, pp. 47-58   |
| Franzini, M.               | Stones in monuments: Natural and anthropogenic deterioration of marble artifacts   | Eur. J. Mineral., 7, pp. 735-743, 1995  |
| Franzini, M., Et al.       | The Stones of medieval buildings in Pisa and Lucca provinces – The Monte Pisano marble.  | Eur. J. Mineral, 2003, 15, pp 217-224, 2003   |
| Fratini, F., Et al.        | Metodi di campionamento ed analisi per lo studio di processi di dedicamento fisico-meccanico di lastre di marmo                                | Convegno su le cave di pietre ornamentali, Torino, 28-29 Nov. 2000  |
| Freedman, S.               | Stone veneer-faced precast concrete panels   | PCI Journal, July-August 2000, pp 72-92   |
| Garzonio, C.A., Et al.     | Analyses of the physical parameters correlated to bending phenomena in marble slabs  | 9th Int. Congress on deterioration and conservation of stone, Venice 19-24 June, 2000   |
| Garzonio, C.A., Et al.     | Analyses of geomechanical decay phenomena of marbles employed in historical monuments in Tuscany   | Mechanics of jointed and faulted rock, ed. Rossmannith, pp. 259-63, 1995  |
| Gauri, K.L., Et al.        | Rate of decay of marble in laboratory and outdoor exposure   | Journal of Materials in Civil Engineering, Vol 1, No. 2, May 1989, P. 73-85   |
| Gennaro, R., Et al.        | Discovering the stone heritage of southern Italy: Technical properties of the Mondragone marble from Campania region.                          | Environmental Geology 44, pp. 266-276, 2003   |
| Gere, A.S.                 | Design considerations for using stone veneer on high-rise buildings.   | STP 996, ASTM, New Stone Technology, Design and Construction for Exterior Wall Systems. 1988  |
| Giafarov, P.F.             | Patologias observadas em revestimentos de fachadas   | Rochas de Qualidade, edição 133, pp. 74-82 (in Portuguese)  |
| Góralczyk, Stefan          | Deformation and defects of marble and limestone cladding.  | Swiat Kamienia, 2003  |
| Grelk, B., Et al.          | The laboratory testing of potential bowing and expansion of marble.  | Proceedings Dimension Stone 2004, International Conference, Prague, Czech Republic. (In prep.), 2004  |
| Grieken, R.V., Et al.      | Modern micro-analytical techniques to elucidate the causes and mechanisms of damage to cultural property.                                      | ?? pp. 101-110  |
| Griffith, J.H.             | Thermal expansion of typical American rocks  | Bulletin 128, Iowa Eng. Experiment Station, Vol. XXXV, No. 19, Oct. 7, 1936   |
| Grimm, W-D.                | Der Alte Südliche und Nördliche Friedhof zu München  | Naturstein, No. 12, pp. 64-69, 1993   |
| Grimm, W-D.                | Marmor als werkstein und denkmalgestein  | Naturstein, No. 12, 1996  |
| Grimm, W-D.                | Zum Steinerweichen   | Naturstein, No. 55, 1994  |

|                                  |  |   |
|----------------------------------|--|---|
| Grimm, Wolf-Dieter               | Beobachtungen und Überlegungen zur Verformung von Marmorobjekten durch Gefügeauflockerung.   | Zeitschrift der Deutschen Geologischen Gesellschaft, Band 150, teil 2, Themenheft: Marmor-Konservierung, pp195-235. 1999                    |
| Guidobaldi, F., Et al.           | Corrosion of marble by rain - The influence of surface roughness, rain intensity and additional washing  | Proc. 5th int congr. on deterioration and conservation of stone vol. 1, ed. G. Felix, Lausanne, France?, pp. 467-474, 1985                  |
| Guidobaldi, F., Et al.           | Corrosion of ancient marble monuments by rain: Evaluation of pre-industrial recession rates by laboratory simulations.                                       | Atmospheric Environment Vol 27B, No. 3, pp. 339-351, 1993.  |
| Hagerman, T.                     | Om svenska bergarter och deras provning för konstruktionsändamål"  | Statens Provningsanstalt, meddelande 85, 5p., 1943  |
| Hatzor, Y.H., Et al.             | Microstructure effects on microcracking and brittle failure of dolomites   | Tectonophysics 281, p. 141-161, 1997  |
| Hawes, F.                        | Designing stone buildings to prevent weathering  | Stone World, Nov., pp. 27-, 1993  |
| Herwegh, Marco                   | A new technique to automatically quantify microstructures of fine grained carbonate mylonites: two-step etching combined with SEM imaging and image analysis | Journal of Structural Geology, 22, pp. 391-400. 2000  |
| Hockman, A., Et al.              | Thermal and moisture expansion studies of some domestic granites   | US Dep. Of Commerce, Nat. Bur. Of Stand. Res. Paper RP 2087, Vol. 44, April, pp. 395-410, 1950  |
| Hoffmann, D., Et al.             | Moisture movement in brick   | Proceeding 5th International Congress on Deterioration and Conservation of stone, 1, Lausanne, 1985   |
| Hoigard, Kurt R., Et al.         | Acceptance performance of thin stone curtain   | The Construction Specifier, December, 1991, pp. 108-115   |
| Hook, G.                         | Look out below - The Amoco Building Cladding Failure   | Progressive Architecture, Feb., 75, pp. 58-62, 1994   |
| Hooker, K.A.                     | Stone Anchoring  | The Constructions Specifications Institute, 1995  |
| Howart, D. F.                    | The effect of pre-existing microcavities on mechanical rock performance in sedimentary and crystalline rocks   | International journal of Rock Mechanics, Mining sciences & Geomechanics, Vol. 24, pp. 223-233, 1987   |
| Howarth, D.F.                    | Experimental study on the relationship between rock texture and mechanical performance   | Trans. Instn Min. Metall., Vol 95, A41- A45   |
| Ihalainen, P.                    | Methods applied in determining the variations of strength and structure of plutonic rock material exposed to artificial weathering treatment                 | Bull. Of the Geol. Soc. Of Finland, No. 65, Part 2, pp. 67-76 1993  |
| Ihalainen, P., et al             | Comparison of weathering resistance of some building stones based on treatments simulating different external conditions                                     | Proc. Seventh Int. Congress International Association of Engineering Geology, September 5-9, 1994, Lisboa, Portugal, 1994                   |
| Iori, I., Et al.                 | La decoesione granulare: problema attuale dei rivestimenti in marmo  | Convegno su le cave di pietre ornamentali, Torino, 28-29 Nov. 2000  |
| Jinyoung, D.                     | Untersuchung der Verwitterung von Fassaden aus Naturstein – Vergleich an den Gebäuden der Museumsinsel in Berlin   | Dem Fachbereich – Chemie – der Technischen Universität Berlin zur Erlangung des akademischen Grades, 2000                                   |
| Johnson, W. H., Et al.           | Thermal expansion of concrete aggregate materials  | National Bureau of Standards Research Paper RP1578, J. of Res. Of Nat. Bur. Of Standards, Vol. 32, March, 1944                              |
| Jones, F.E.                      | The structure and properties of aggregates   | Third Int. Symp. On Chem. Of Cement, C&CA, England, pp. 378-387 + 416-417, 1952   |
| Jornet, A., Rück, P.             | Bowing of Carrara marble slabs: a case study   | Quarry-Laboratory-Monument Int. Congress, Pavia, Vol. I, pp. 355-360. 2000  |
| Karhapää, E., Et al.             | Weather resistance tests of carrara type white marble  | VTT, building technology, RTE5-IR-2/1994, 1994  |
| Kathol, Benno                    | Byggstensforskning: Marmor i Stockholms innerstad (Marble in the city of Stockholm)  | Institutionen för Geologi och Geokemi, Stockholm Universitet, Stockholm, 1992   |
| Kellermeyer, K., Et al.          | Lessons learned from investigations of over 500 distressed masonry and stone facades   | Proceedings of Symposium on Performance of Building Constructions, ASTM, P. 152-164, 1983   |
| Kessler, D.W.                    | Physical and chemical tests on the commercial marbles of the united states   | Technologic papers of the bureau of standards No. 123, 1919   |
| Kessler, D.W. and Anderson, R.E. | Stone Exposure Test Wall   | Building Materials and Structures Report 125, September 20, 1951  |
| Koch, A., Et al.                 | Bowing of marble panels: On-site damage analysis from the Oeconomicum Building at Göttingen (Germany)  | Natural Stone, Weathering Phenomena, Conservation Strategies and Case Studies, Geological Society Special Publication No. 205, London 2002. |
| Koch, A, et al                   | The combined effect of moisture and temperature on the anomalous expansion behaviour of marble.  | In prep. (2003)   |
| Kouri, M., Et al.                | Cholesteric liquid crystals as weathering indicators for marble surfaces.  | Liquid Crystals, Vol. 27, No. 12, pp. 1561-1571, 2000.  |

|                             |   |  |
|-----------------------------|---|--|
|                             |   |  |
| Kourkoulis, S.K., et al.    | U-notched Dionysos-Pentelicon marble beams in three point bending: The effect of nonlinearity, anisotropy and microstructure.                     | International Journal of Fracture 98, 1999, pp. 369-392, 1999  |
| Koutsoukos, P.G.            | Physicochemical investigations modelling marble deterioration.  | Proc. Eurocare – Euromarble. EU 496 – Workshop 7. October 1996, Patras, Greece.  |
| Krishna Rao, Et al.         | Precision lattice parameters and thermal expansion of calcite.  | J. Phys. Chem. Solid, 29, pp. 245-248, 1968  |
| Kunze, K., Et al.           | Orientation imaging microscopy of calcite rocks   | Textures of Geological Materials, Informationsgesellschaft Verlag, 1994, ISBN 3-88355-200-3                                  |
| Kunze, K., Et al.           | Texture development of calcite by deformation and dynamic recrystallization at 1000 K during torsion experiments of marble to large strains.      | Tectonophysics, 330, 2001, pp. 119-140   |
| Kurz, W. Et al.             | Microstructural and textural development of calcite marbles during polyphase deformation of Penninic units within the Tauern Window (Eastern Alp) | Tectonophysics 316, 2000, pp. 327-342  |
| Larkin, J.H.                | Edge spalling in thin cladding  | Degradation of Natural Building Stone, Geotechnical Special Pub. No. 72, ASCE. 1997  |
| Leiss, B., Et al.           | Texture asymmetries as shear sense indicators in naturally deformed mono- and polyphase carbonates  | Textures & Microstructures, 33, pp. 61-74, 1999  |
| Lemvig, J., et al           | Natural stone panels for building facades – Loss of strength caused by temperature cycles   | Proceedings of the 6 <sup>th</sup> Symposium on Building Physics in the Nordic Countries, Trondheim, June 17-19, 2002        |
| Levy, M., Et al.            | Bowing of thin marble   | Stone Industries, April, pp 44-50. 1994  |
| Lewis, M.D.                 | Choosing stone cladding for building facades  | Stone World, March, pp. 44. 1995   |
| Lindborg, U.                | Fatigue-induced shape change in marbele   | Mechanisms and mechanics of Fracture – The John Knott Symposium, 2002  |
| Liu, J., Et al.             | Fluid-enhanced low-temperature plasticity of calcite marble: Microstructure and mechanisms.   | Geology, September 2002. pp. 787-790.  |
| Logan, J.M., Et al.         | A case study of the properties of marble as building veneer   | International journal of Rock Mechanics, Mining sciences & Geomechanics, Vol. 30, pp. 1531-1537. 1993                        |
| Malaga-Starzec, Et al       | Experimental study on the variation in porosity of marble as a function of temperature  | Natural Stone, Weathering Phenomena, Conservation Strategies and Case Studies, Geol. Soc. Special Pub. No. 205, London 2002. |
| Malaga-Starzec, Et al       | Experimental study on the variation in porosity of marble as a function of temperature  | The Conservation of Cultural Heritage for Sustainable Development, 2003  |
| Malaga-Starzec, Et al       | Field exposure sites and accelerated laboratory test of marble panels.  | Proceedings Dimension Stone 2004, International Conference, Prague, Czech Republic. (In prep.) (2004)                        |
| Mamillan, M.                | Methods for assessing the deterioration of stone monuments  | ???, pp. 90-99   |
| Mamillan, M.                | Recent knowledge of the physical properties of building stones  | Industrie Minérale - Les Techniques, pp. 287-299, 1982   |
| McGee, E.S.                 | Influence of microclimate on the deterioration of historic marble buildings   | APT (Association Preservation Techno-logy) Bulletin, Vol. XXIII, pp. 37-42, 1991   |
| McGee, E.S.                 | Philadelphia Merchants' Exchange Conservation Strategy: Marble Characteristics and Deterioration  | U.S. Geological Survey - open-file report 96-519   |
| McGee, E.S.                 | Colorado Yule Marble – Building stone of the Lincoln Memorial   | U.S. Geological Survey Bulletin 2162, 1999   |
| McNeill, G.W.               | Variations in the weathering rate of Scottish gravestones as an environmental signature of atmospheric pollution.                                 | Environmental Geochemistry and Health, 21, 1999, pp. 365-370   |
| Michalopoulos, A.P., Et al. | Influence of water on hardness, strength and compressibility of rock  | Bull. Of the Ass. Of Eng. Geologists, Vol. XIII, No. 1, pp. 1-22. 1976   |
| Mirwald, P.W.               | Evaluating damage and accelerated exposure and field studies: Modelling techniques  | ???, pp. 111-123   |
| Mobbs, S.F., Et al.         | Low temperature thermoluminescence of marble and its possible correlation with stress history   | Modern Geology, 8, pp. 149-154. 1984   |
| Molli, G.                   | The Microstructures of the Alpi Apuane Marbles and their Tectonic setting: A preliminary note   | Atti Soc. Tosc. Sci. Nat., Mem., Serie A, 105, pp. 49-56. 1998   |

|                             |  |  |
|-----------------------------|--|--|
| Molli, G. Et al.            | Microfabric study on the deformational and thermal history of the Alpi Apuane marbles (Carrara marbles), Italy   | Journal of Structural Geology, 22, pp. 1809-1825. Elsevier Science Ltd. 2000   |
| Molli, G; Heilbronner, R.   | Microstructures associated with static and dynamic recrystallization of Carrara marble (Alpi Apuane, NW Tuscany, Italy)  | Geologie en Mijnbouw, 78, pp. 119-126. 1999  |
| Molli, G., Meccheri, M      | Structural setting in the upper Colonnata valley: An example of polyphasic and composite deformation from the Alpi Apuane (in Italian)                         | Boll. Soc. Geol. It., volume 119 (2000), pp. 379-394   |
| Molnárka, G., Et al.        | The methodology in visual examinations in building pathology.  | Budapest, Hungary.   |
| Morandini_A.F. & Marini, P. | Criteria for the assessment of stone behaviour in buildings  | Georisorse Minerarie – GEAM<br>Giugno-Settembre 2000   |
| Mukhopadhyaya, P., Et al.   | Performance: Predict the moisture management<br>Performance of wall system as a function of climate, material properties, etc. through mathematical modelling. | Institute for Research in Construction – IRC-RR-132, MEWS Task 7 – final report – February 2003                      |
| Nolen-Hoeksema R., Et al.   | Optical Detection of Crack Patterns in the Openin-Mode Fracture of Marble  | Int. J. Rock Mech. Sci. & Geomech., 24, pp. 135-144. 1987  |
| Nordtest                    | NT Build 499 Cladding panels: Test for bowing  | Published by Nordtest, Tekniikantie 12, Espoo, Finland – <a href="http://www.nordtest.org">www.nordtest.org</a> 2002 |
| Nordtest                    | NT Build 500 Cladding panels: Filed method for measurement of bowing   | Published by Nordtest, Tekniikantie 12, Espoo, Finland - <a href="http://www.nordtest.org">www.nordtest.org</a> 2002 |
| Normandin, K.C., Et al.     | Stone cladding technology: Monitoring and intervention techniques for stabilization.   | Historic Constructions, Guimarães, 2001  |
| Ordaz, J., Esbert, R.M.     | Porosity and capillarity in some sandstone and dolomite monumental stones  | Proc. 5th Int. Congress on Deterioration and Conservation of stone, 1, Lausanne. 1985                                |
| Orkoula, M.G., Et al.       | Dissolution of Pentelic marble at alkaline pH.   | Langmuir, 16, 2000, pp. 7263-7267<br>American Chemical Society. 2000   |
| Orkoula, M.G., Et al.       | Dissolution effects on specific surface area, particle size, and porosity of Pentelic marble.  | Journal of Colloid and Interface Science, 239, pp. 483-488, 2001   |
| Pauly, A.B.                 | Fassadenbekleidung mit hinterlüfteten Marmorplatten  | Bauschäden-Sammlung, Band 12, 1999   |
| Perrier, R., Bouineau, A.   | La decohesion granulaire menace pour les façades en marbre.  | Le Mausolee 9. 1995  |
| Perrier, R.                 | Measure de la décohesion thermique des marbres par l'attenuation des vibrations en flexion   | TechniPIERRE 96 – Problematique des Pierres dans la Restauration des Monuments. 1996                                 |
| Perrier, R., Et al.         | Thermal decohesion in marble and marmoreal limestone   | <a href="http://www.informstone.es/t4.html">www.informstone.es/t4.html</a> , 21 p. 1999                              |
| Perrier, R.                 | La descohesion térmica en mármoles y calizas marmóreas, pp. 59-71  | Investigacion y Desarrollo. 1997   |
| Pfeifer, M.                 | Naturstein an der Aussenwand   | Sachverständiger für Schäden an Fassaden, Dresden, 2002  |
| Polikreti, K., Et al.       | Thermoluminescence characteristics of marble and dating of freshly excavated marble objects.   | Radiation Measurements, 37, 2003, pp. 87-94.   |
| Polikreti, K., Et al.       | Micromorphology, composition and origin of the orange patina on the marble surfaces of Propylaea (Acropolis, Athens).  | The Science of the Total Environment, 308, 2003, pp. 111-119.  |
| Quick, G.                   | CSIRO, Selective guide to the specification of Dimension Stone.  | CSIRO Building, Construction and Engineering, Highett, Victoria, Australien. 2002                                    |
| Rayleigh, L.                | The bending of marble  | The Royal Society of London, p. 266-279. 1933  |
| Realini, M., Et al.         | Deposition of particulate matter on stone surfaces: an experimental verification of its effects on Carrara marble.   | The Science of the Total Environment, 167, 1995, pp. 67-72. 1995   |
| Redding, J, Et al.          | Slimming down  | Stone Industries, March, pp 20-23. 1994  |
| Ridout, G.                  | Thin stone cladding defects  | Technical Forum Building Technical File No. 26 July. 1989  |
| Rink, M. Et al.             | Pore structure and physical properties of porous sedimentary rocks   | Pageoph, Vol. 114 , Basel. 1976  |
| Rodrigues, J.D              | Causes, Mechanisms and measurement of damage in stone monuments  | ???, pp. 125-137   |
| Rosenholz, J.L., Et al.     | Linear thermal expansion of calcite, Var. Iceland Spar, and Yule marble.   | The American Mineralogist, 34, P. 846-854. 1949  |
| Rossi-Doria, P.             | Pore structural analysis in the field of conservation: state of the art and future developments  | C.N.R. Centro "Conservazione Opere d'Arte, Roma, Italia, 32pp.   |

|                               |   |   |
|-------------------------------|---|---|
| Rossi-Doria, P, Et al.        | Viellissement naturel et artificiel des pierres: Eventuelles relations decelables a l'aide de mesures porosimetriques   | The conservation of stone I, International symposium, Bologna, ed. Rossi-Manaresi, pp.749-61. 1976  |
| Royen, N.                     | Naturstenens tekniska egenskaber och dess användning till husbyggnader och skyddsrumsläggningar (in Swedish)  | Transactions of Chalmers University of Technology, Gothenburg, no. 8, p. 16. 1942   |
| Royen, N.                     | Undersökningar rörande sprickbildningar i kalkstensplattor (Investigation of crack-formation in limestone plates, in Swedish)   | Byggmästaren, nr. 16, Allmänna Uppl. 11, pp. 81-84. 1933  |
| Royer-Carfagni, G., Et al.    | The characterization of marble by cyclic compression loading: experimental results  | Mechanics of cohesive-frictional materials, 6th March, pp. 29. 2000   |
| Royer-Carfagni, G.            | A model for the characterization of damage in cyclically loaded stones  | XIV congresso nazionale dell'associazione italiana di meccanica teorica ed applicata, Como. 6-9 Ottobre. 1999                               |
| Royer-Carfagni, G.            | Some considerations on the warping of marble facades: the example of Alvar Aalto's Finland Hall in Helsinki   | Construction and Building Materials, 13, pp. 449-57. 1999   |
| Royer-Carfagni, G.F.          | On the thermal degradation of marble  | International journal of Rock Mechanics and Mining sciences, 36, pp. 119-126. 1999  |
| Ruedrich, J., Et al.          | Thermal behaviour of weathered and consolidated marbles   | Natural Stone, Weathering Phenomena, Conservation Strategies and Case Studies, Geological Society Special Publication No. 205, London 2002. |
| Sage, J.D.                    | Thermal microfracturing of marble   | Engineering Geology of Ancient Works, Monuments and Historical Sites, pp. 1013-1018. 1988   |
| Sarsano, R.                   | L'applicazione del marmo nei rivestimenti di facciata: analisi di laboratorio e studio del costruito per la prevenzione del degrado legato alle deformazioni permanenti | Tesi di Laurea, Politecnico di Torino, Facoltà di Ingegneria 1998   |
| Schaffer, R.J.                | The Weathering of Natural Building Stones   | Building Research, special report No. 18. 1932  |
| Scheffler, M.J. Et al.        | Natural weathering of granite: A case study   | STP 1394 Dimension Stone Cladding: Design, Construction, Evaluation and Repair, November, pp 79-94. 2000                                    |
| Schouenborg, B. Et al.        | TEAM – Testing and assessment of marble and limestone cladding.   | IBMS 2003 Conference "International Symposium of Industrial Minerals and Building Stones, Istanbul, September 2003.                         |
| Shadmon, A.                   | Environmental implications of surface treatment of building stones and ornamental rocks   | 7th International IAEG Congress, Balkema, Rotterdam pp. 3677-3682. 1994   |
| Sheremeti-Kabashi, F. Et al.. | Determination of structural anisotropy of Carrara marble with ultrasonic measurements   | 9th Int. Congress on deterioration and conservation of stone, Venice 19-24 June. 2000   |
| Sherwood, S.I., Et al         | Acidic deposition and marble monuments at Gettysburg National Military Park   | ATP Bulletin No. 4, 1991  |
| Siegesmund, S, Et al.         | Marble as a natural building stone: rock fabrics, physical and mechanical properties  | Zeitschrift der Deutschen Geologischen Gesellschaft 150 (2) pp. 237-258. 1999   |
| Siegesmund, S., Et al.        | Deterioration characteristics of columns from the Marmorpalais Potsdam (Germany) by ultrasonic-tomography   | Proceedings 19. Int. Congress Deterioration of Stones, Venice, Elsevier (in press). 2000  |
| Siegesmund, S., Et al.        | Physical weathering of marbles caused by anisotropic thermal expansion  | Int. J. Earth Sciences, 89, pp. 170-182. 2000   |
| Siegesmund, S., Et al.        | Marmorpalais wird originalgetreu restauriert  | Naturstein, 5, 2001, pp. 92-101   |
| Siegesmund, S., Et al.        | Control of marble weathering by thermal expansion and rock fabrics  | Proceedings 19. Int. Congress Deterioration of Stones, Venice, Elsevier (in press). 2000  |
| Slaton, D., Scheffler, M.J.   | Failures. Why things bow  | <a href="http://www.csinet.org">www.csinet.org</a> (2001)   |
| Smith, M.R.                   | Stone: Building stone, rock fill and armourstone in construction  | The Geological Society, pp. 475. 1999   |
| Solinski, Joseph P.           | Thin stone veneer/Study and remediation   | STP 1394 Dimension Stone Cladding: Design, Construction, Evaluation and Repair, November, pp 161-177. 2000                                  |
| Sorace, S                     | Long-term tensile and bending strength of natural building stones   | Materials and Structures, Vol 29, August/September, pp 426-435. 1996  |
| Sraeel, Holly                 | Who's liable if an exterior building system fails   | Buildings, 5/1/1990   |
| Srinivas, S.Y., Et al.        | Weathering rates of marble in laboratory and outdoor conditions.  | Journal of Environmental Engineering, September 1996, pp. 856-863.  |
| Stambolov, T., Et al.         | The deterioration and Conservation of Porous Building materials in Monuments. A Preliminary Review.   | Central Research Laboratory for Objects of Art and Science, Amsterdam. 1967   |
| Stocksiefen, W.               | Hinterlüftete Fassensbekleidung mit Marmorplatten. Konkave Verformung, Rissbildung, Ausbrüche.  | Bauschäden-Sammlung, Band 8, pp 76-78 1991  |



|                        |  |   |
|------------------------|--|---|
| Stocksiefen, W.        | Marmorschäden:Analyse und therapie   | Naturstein, No.12, 1996   |
| Stocksiefen, W.        | Naturwerksteinfassaden des Marienhospital in Lünen   | Internal report, 1991   |
| Strohmeier, D., Et al. | Anisotropic technical properties of building stones and their development due to fabric changes.   | Natural Stone, Weathering Phenomena, Conservation Strategies and Case Studies, Geological Society Special Publication No. 205, London 2002. |
| Stutzman, P.E., Et al. | Stone exposure test wall at NIST   | Degradation of Natural Building Stone, Geotechnical Special Publ. No. 72, ASCE. 1997  |
| Suenson, E             | Byggematerialer, Natursten, 3rd volume   | Jul. Gjellerups Forlag, København. 1942   |
| Thomasen, S.E., Et al. | Durability of thin-set marble  | Proc. 3rd int. conf. on durability of building materials and components, ASTM, pp. 313-323. 1984  |
| Thomasen, S.E., Et al. | Assessment of building facades in masonry and stone  | ASTM STP 1098, eds. Kelley and Marshall, pp. 108-116. 1990  |
| Tiano, P., Et al.      | Nuove tecniche di valutazione del grado di coesione di superfici lapidee   | Manutenzione e Conservazione del Costruito fra Tradizione e Innovazione (Bressanone), pp. 527-534. 1986                                     |
| Tolstoy, N., Et al.    | Formändringar hos vit Carrara-marmor   | Forskningsrapport BFR 950430-7<br>AB Jacobson & Widmark, Stockholm 1997   |
| Tournier, B., Et al.   | Stone drying: an approach of the effective evaporating surface area  | 9th International Congress on deterioration and conservation of stone, Venice 19-24 June, 2000  |
| Trewhitt, J., Et al.   | Amoco may replace marble on Chicago headquarters   | ENR, march 24, pp. 11-12. 1988  |
| Tschegg, K.E., Et al.  | Ursachen mangelnder formbeständigkeit von marmorplatten  | "Zeitschrift der Deutscher Geologischer Gesellschaft, 150/2, p 283-297. 1999  |
| Tschegg, K.E           | Prevention of deformation of marble cladding panels.   | Craft Synthesis Report for Publication.<br>Project No: CR-1815-91. Contract No: BRE2-CT94-1559. 1997  |
| Turner, A.             | Repair to Jones Hall's weak facade walls nearing end \$24 million project enters final phase   | Houston Chronicle, Monday, June 23th, 2003  |
| Turner, F.J., Et al.   | Experimental deformation of calcite crystals   | Bulletin of the geological society of America, vol. 65, pp. 883-934. 1954   |
| Turner, F.J.           | Preferred orientation of calcite in Yule marble  | American Journal of Science, September 1949   |
| Vitruvius, M.          | De Architectura Libri Decem - Marcus Vitruvius Pollio: de Architectura, Book II.   | English translation by Frank Granger, Harward University Press, 1931  |
| Vogt, J.H.L.           | Norsk marmor (Norwegian marble)  | Norges Geologiske Undersøgelse No. 22. 1897   |
| Weaver, T.             | Country officials fix on buildings' woes; Tobacco money may be used to repair problems such as falling bricks, duct-taped rail.              | The Post-Standard (Syracuse, NY), 11/30/2001  |
| Wedhorn, L.            | Marmor Platten die sich biegen   | Stein, No. 1, 1992  |
| Weiss, T., Et al.      | Microfabric of fresh and weathered marbles: Implications and consequences for the reconstruction of the Marmorpalais Potsdam                 | Z. Deutsch. Geol. Ges. 150 (2) pp. 313-332. 1999  |
| Weiss, T., Et al.      | Microfabric of fresh and weathered marbles and its implication on the weathering phenomena observed at the Marmorpalais in Potsdam (Germany) | Zeitschrift der Deutschen Geologischen Gesellschaft, Band 150, Teil 2, Themenheft: Marmor-Konservierung. Stuttgart 1999                     |
| Weiss, T., Et al.      | Thermal degradation of marble: Indications from finite-element modelling   | Building and Environment, No. 38, pp. 1251-1260, 2003.  |
| Weiss, T., Et al.      | The relationship between deterioration, fabric, velocity and porosity constraint.  | Proceedings 19. Int. Congress Deterioration of Stones, Venice, Elsevier (in press). 2000  |
| Wheeler, N.E.          | On the thermal expansion of rock at high temperatures  | Transactions of the Royal Society of Canada, Ser. III, iv. 1910   |
| Widhalm, C., Et al.    | Acoustic emission and anisotropic expansion when heating marble  | Journal of the performance of constructed facilities, 11(1), pp. 1-6. 1997  |
| Widhalm, C., Et al.    | Anisotropic thermal expansion causes deformation of marble claddings   | Journal of the performance of constructed facilities, 10(1), pp. 5-10. 1996   |
| Widhalm, C., Et al.    | Methods for determining the preferred orientation in crystalline calcite marble.   | Proc. Eurocare – Euromarble, EU 496 – Workshop 7, October 1996, Patras, Greece.   |
| Widhalm, C., Et al     | Messmethoden zur Beschreibung von Gefügeanisotropien in Marmor.  | Z. Deutsch. Geol. Ges. 150 (2) pp. 313-332. 1999  |
| Willis, T.F., Et al.   | Thermal volume change and elasticity of aggregates and their effect on concrete  | ?   |



|                         |   |  |
|-------------------------|---|--|
|                         |   |  |
| Winkler, E.M.           | A durability index for stone  | Proceeding 5th International Congress on Deterioration and Conservation of stone, 1, Lausanne, p 151-156. 1985                                   |
| Winkler, E.M.           | Buttressed expansion in granitic rocks in the field and on buildings  | 4. Int. Kolloquium Werkstoffwissenschaften und Bauinstandsetzen, pp. 537-542. 1996   |
| Winkler, E.M.           | Properties of marble as a building material   | Int. J. Rock Mech. Min. Sci. & Geomech. Abstr. 33(2), pp. 215-18. 1996   |
| Winkler, E.M.           | Stone in Architecture   | Springer Verlag p. 300+. 1994  |
| Winkler, E.M.           | The Complex Cause of Bowing of Marble and Granite Panels  | STP 1394, ASTM Symposium on Dimension Stone Cladding: Design, Evaluation, Construction and Repair. pp. 71-78. October 27. New Orleans, 1999      |
| Winkler, E.M.           | Weathering of crystalline marble  | Engineering geology of ancient works, monumnets and historical sites, ed. Marinos, P.G., and Koukis, G.C., Balkema, Rotterdam, pp. 717-721. 1988 |
| Winkler, E.M.           | Weathering of crystalline marble at the field museum of Natural History, Chicago  | APT Bulletin (The Assoc. Preservation Technoco, Vol. XXIII, No.4). 1991  |
| Wonneberger, B., Et al. | Comparing Laboratory and Field Durability Testing of Stone  | 8th Int. Conf. On Durability of Building Materials and Components, Vancouver, Canada. 1999   |
| Yates, T.J.S., Et al.   | Lightweight veneer stone cladding panels  | BRE Information paper; IP 17/98. 1998  |
| Yates, T.J.S., Et al.   | Stone cladding panels: in-situ weathering   | BRE Information paper; IP 18/98. 1998  |
| Yates, T., Et al.       | Observations from the inspections of marble cladding in Europe.   | Proceedings Dimension Stone 2004, International Conference, Prague, Czech Republic. (In prep.)   |
| Zeizig, A. Et al.       | Thermal expansion and its control on the durability of marbles  | Natural Stone, Weathering Phenomena, Conservation Strategies and Case Studies, Geological Society Special Publication No. 205, London 2002.      |
| Zeza, U., Et al.        | Effect of temperature on intergranular decohesion of the marbles  | Proc. 5th int congr. on deterioration and conservation of stone vol. 1, ed. G. Felix, Lausanne, France?, pp. 131-140. 1985                       |
| Zeza, U.                | Decay evolution depending on the textural anisotropy of marbles in monuments  | Proc. 2nd International Symposium, The conservation of monuments in the Mediterranean Basin, pp. 289-302. 1991                                   |
| Zeza, U.                | Influence of mechanical anisotropic behaviour to tensile strength on decay evolutions of marbles in monuments                                   | Conservations of Stones and Other Materials, RILEM, pp. 220-226. 1993  |
| Zeza, U.                | L'anisotropia fisico-meccanica delle pietre da costruzione e il rilevamento in situ sul patrimonio architettonico a mezzo prove non distruttive | Atti Conv. Int. "Il recupero degli edifici antichi. Manualistica e nuove tecnologie" (Napoli), pp. 425-432. 1993                                 |
| Zhang, S., Et al.       | Microcrack growth and healing in deformed calcite aggregates.   | Tectonophysics, 335, 2001, pp. 17-36.  |
| Zimmermann, G.          | Schäden an Belägen und Bekleidungen mit Keramik- und Werksteinplatten.<br>Abschnitt von Verwölbung von Marmor-Fassadenplatten.                  | Schadenfreies Bauen, Band 25, 2001   |